Serial No. 10/609,473

IN THE SPECIFICATION:

Page 9, line 9, please replace with the following:

FIG. 14 is a diagram showing coil arrangement in a conventional three-phase short-pitch concentric-winding brushless motor- $\frac{1}{2}$

FIG. 15 is a diagram showing teeth present in three times the number of pole elements.

Page 9, lines 14-17, please replace with the following:

FIG. 1 shows the arrangement of coils of a stator in a three-phase full-pitch-winding brushless motor in which the number of poles of a rotor is 6 and the number of slots in the stator is 18. FIG. 15 shows stator 10 including eighteen teeth 11 and six pole elements 12.